

2019



2019

MULTI-POINT INSPECTION

VEH#: 17-519 Mileage: 5420 Year/Make/Model: 2019 charger
 WO#: 10225 VIN: _____ License: _____ email: _____

■ CHECKED AND OK ■ FUTURE ATTENTION ■ IMMEDIATE ATTENTION

INTERIOR/EXTERIOR	
NOTE ANY EXISTING BODY DAMAGE	
Lights (Head, Brake, Turn, Parking)	■ ■ ■
Windshield / Glass	■ ■ ■
Wipers	■ ■ ■
Horn / Interior Lights	■ ■ ■

TIRES	
TREAD DEPTH	
■ 7/32" or greater	■ 3/32" to 6/32"
■ 2/32" or less	
LF ■ ■ ■ 9/32"	RF ■ ■ ■ 9/32"
LR ■ ■ ■ 9/32"	RR ■ ■ ■ 9/32"
	Wear Pattern / Damage LF ■ ■ ■ RF ■ ■ ■ LR ■ ■ ■ RR ■ ■ ■
	Air Pressure BEFORE SHOULD BE LF <input type="text"/> <input type="text"/> RF <input type="text"/> <u>35</u> LR <input type="text"/> <input type="text"/> RR <input type="text"/> <u>35</u>
	Based on Mileage and Wear: <input type="checkbox"/> Alignment <input checked="" type="checkbox"/> Balance <input type="checkbox"/> Rotation <input type="checkbox"/> New Tire

BATTERY	
■ ■ ■	

BRAKES	
BRAKE PADS / SHOES	
■ Over 5 mm (Disk) or 2 mm (Drum)	
■ 3-5 mm (Disk) or 1.01-2 mm (Drum)	
■ Less than 3 mm (Disk) or 1 mm (Drum)	
LF ■ ■ ■ RF ■ ■ ■ LR ■ ■ ■ RR ■ ■ ■	

UNDERHOOD	
Oil Condition	■ ■ ■
Transmission Fluid	■ ■ ■
Power Steering / Brake Fluid	■ ■ ■
Coolant / Antifreeze	■ ■ ■
Air Filter	■ ■ ■
Cabin Filter	■ ■ ■
Belts	■ ■ ■

UNDER VEHICLE	
Brake Lines / Brake Hoses / Brake Cables / Fuel Lines	■ ■ ■
Suspension & Steering	■ ■ ■
Driveline (Axles / CV Shaft)	■ ■ ■
Rear Differential Fluid Level & Condition	■ ■ ■
Exhaust System / Shocks & Struts	■ ■ ■

COMMENTS	

Inspected by: [Signature] Date: 11/20/19