

Received

2023

MAR 24 2023

LCPW Motor Pool



2023

MULTI-POINT INSPECTION

VEH#: 17-721 Mileage: 15,447 Year/Make/Model: _____
 WO#: 16707 VIN: _____ License: _____ email: _____


☒ CHECKED AND OK

☐ FUTURE ATTENTION

☐ IMMEDIATE ATTENTION

INTERIOR/EXTERIOR

NOTE ANY EXISTING BODY DAMAGE




Lights (Head, Brake, Turn, Parking)



Windshield / Glass





Wipers



Horn / Interior Lights




BATTERY



UNDERHOOD

Oil Condition

Changed

Transmission Fluid




Power Steering / Brake Fluid



Coolant / Antifreeze



Air Filter



Cabin Filter



Belts



UNDER VEHICLE

Brake Lines / Brake Hoses /
Brake Cables / Fuel Lines

Suspension & Steering



Driveline (Axles / CV Shaft)



Rear Differential Fluid Level & Condition



Exhaust System / Shocks & Struts



TIRES

TREAD DEPTH

☒ 7/32" or greater

☐ 3/32" to 6/32"

☐ 2/32" or less
LF ☒ ☐ ☐ 9/32"RF ☒ ☐ ☐ 9/32"LR ☒ ☐ ☐ 8.5/32"RR ☒ ☐ ☐ 8.5/32"Wear Pattern/
DamageLF ☒ ☐ ☐RF ☒ ☐ ☐LR ☒ ☐ ☐RR ☒ ☐ ☐

Air Pressure

☒ (!)

BEFORE SHOULD BE


LF ☐ ☐ 35RF ☐ ☐ 35LR ☐ ☐ 35RR ☐ ☐ 35Based on
Mileage
and Wear:☐ Alignment☐ Balance☐ Rotation☐ New Tire

BRAKES

BRAKE PADS / SHOES

☒ Over 5 mm (Disk)
or 2 mm (Drum)

☐ 3-5 mm (Disk)
or 1.01-2 mm (Drum)

☐ Less than 3 mm (Disk)
or 1 mm (Drum)
LF ☒ ☐ ☐RF ☒ ☐ ☐LR ☒ ☐ ☐RR ☒ ☐ ☐

COMMENTS

 Inspected by: Keith Date: 3-21-23