2019 CENTRAL SHOP EQUIPMENT SAFTEY INSPECTION

Equipment # 26 -103	Equipment Description:	SP 310 BACKLOC	License # > 4429C
Inspection Date : 6-25-19	Year 2005	Mileage	Machine Hours <u>562</u> 6
Fire Extinguisher : Size 24	15 Date 2015	Type ABC	

ck OK	ltem	Comments or Corrections Needed
	Vehicle Accident Report	
	Oversize load sign	(if required)
~	County Required Decals	
V	First Aid Kit	UPDATED
	Flagging Paddle	(if required)
	Road Warning Devices	(if required)
	Litter Bag	(if required)
	Seatbelt Condition	
V	Horn: Air and/or Electric	
<u></u>	Window condition	
1	Wipers and Washers	
/	Mirrors	
<u> </u>	4 - Way Flashers	
V	Turn Indicators	
	Low Air Warning	
	Snow Plow Headlights	
V	Headlights	ORUERD LEFT Front WORK LIGH
	Tail Lights	
V	Brake Lights	
	Back up Lights	
	Clearance Lights	
V		
	Lic. Plates Legible + Light	(if required)
2	Back Up Alarm	
	Chock Blocks	
V	Fuel System (Tank, Cap, & Leaks)	
	Air System: Leaks & operation	
V	Engine Oil Leaks	
V	Hydraulic System: leaks & operation	REPIRCED RighT OUTRINGE/ CYL
	Exhaust System	
~	Tire Condition	
V	Wheel/ Rim/ Lugnut/ Track Condition	
L	Frame Condition	
	Coupling Devices:	
	Fifth wheel plate, chipspreader & pintle hitch	<u></u> -
V	Steering System	
	Drop Axle Assembly	
	Brakes: wear and Adjustment	
	Parking Brake: Operation & Adjustment	
	Inspector	Signature (Symples)
litions	Comments	