

2020



2020

MULTI-POINT INSPECTION

VEH#: 17-519 Mileage: 25,551 Year/Make/Model: 2019 chrysler
 WO#: 11741 VIN: _____ License: _____ email: _____

■ CHECKED AND OK ■ FUTURE ATTENTION ■ IMMEDIATE ATTENTION

INTERIOR/EXTERIOR

NOTE ANY EXISTING BODY DAMAGE

Lights (Head, Brake, Turn, Parking)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Windshield / Glass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Wipers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Horn / Interior Lights	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

TIRES

TREAD DEPTH

■ 7/32" or greater ■ 3/32" to 6/32" ■ 2/32" or less
 LF 6/32" RF 6/32"
 LR 7/32" RR 7/32"

Wear Pattern/ Damage

LF

RF

LR

RR

Air Pressure

BEFORE		SHOULD BE
LF	<input type="checkbox"/>	35
RF	<input type="checkbox"/>	35
LR	<input type="checkbox"/>	35
RR	<input type="checkbox"/>	35

Based on Mileage and Wear:

Alignment

Balance

Rotation

New Tire

BATTERY

UNDERHOOD

Oil Condition	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Transmission Fluid	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Power Steering / Brake Fluid	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Coolant / Antifreeze	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Air Filter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Cabin Filter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Belts	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

BRAKES

BRAKE PADS / SHOES

■ Over 5 mm (Disk) or 2 mm (Drum)
■ 3-5 mm (Disk) or 1.01-2 mm (Drum)
■ Less than 3 mm (Disk) or 1 mm (Drum)

LF	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
RF	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
LR	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
RR	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

UNDER VEHICLE

Brake Lines / Brake Hoses / Brake Cables / Fuel Lines	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Suspension & Steering	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Driveline (Axles / CV Shaft)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Rear Differential Fluid Level & Condition	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Exhaust System / Shocks & Struts	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

COMMENTS

Next service new tires

Inspected by: [Signature] Date: 8/11/20