

2021



2021

# MULTI-POINT INSPECTION

VEH#: 17-519 Mileage: 41,113 Year/Make/Model: 2019 Charger  
 WO#: 12889 VIN: \_\_\_\_\_ License: \_\_\_\_\_ email: \_\_\_\_\_

■ CHECKED AND OK      ■ FUTURE ATTENTION      ■ IMMEDIATE ATTENTION

### INTERIOR/EXTERIOR

NOTE ANY EXISTING BODY DAMAGE

Lights (Head, Brake, Turn, Parking)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Windshield / Glass	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Wipers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Horn / Interior Lights	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

### TIRES

#### TREAD DEPTH

■ 7/32" or greater    ■ 3/32" to 6/32"    ■ 2/32" or less

LF	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	RF	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
LR	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	RR	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Wear Pattern / Damage		Air Pressure		Based on Mileage and Wear:
LF	<input checked="" type="checkbox"/>	BEFORE	SHOULD BE	
RF	<input checked="" type="checkbox"/>	LF	<input type="checkbox"/> 40	<input type="checkbox"/> Alignment
LR	<input checked="" type="checkbox"/>	RF	<input type="checkbox"/>	<input type="checkbox"/> Balance
RR	<input checked="" type="checkbox"/>	LR	<input type="checkbox"/> 40	<input checked="" type="checkbox"/> Rotation
		RR	<input type="checkbox"/>	<input type="checkbox"/> New Tire

### BATTERY

### BRAKES

#### BRAKE PADS / SHOES

■ Over 5 mm (Disk) or 2 mm (Drum)  
■ 3-5 mm (Disk) or 1.01-2 mm (Drum)  
■ Less than 3 mm (Disk) or 1 mm (Drum)

LF	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
RF	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
LR	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
RR	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

### UNDERHOOD

Oil Condition	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Transmission Fluid	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Power Steering / Brake Fluid	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Coolant / Antifreeze	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Air Filter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Cabin Filter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Belts	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

### UNDER VEHICLE

Brake Lines / Brake Hoses / Brake Cables / Fuel Lines	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Suspension & Steering	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Driveline (Axles / CV Shaft)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Rear Differential Fluid Level & Condition	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Exhaust System / Shocks & Struts	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

### COMMENTS

Transmission PM

Wiper blades

Inspected by: [Signature] Date: 3-9-21