

2022



2022

MULTI-POINT INSPECTION

VEH#: 13-117 Mileage: 43,858 Year/Make/Model: 2017 RAM

WO#: 14815 VIN: _____ License: _____ email: _____

■ CHECKED AND OK ■ FUTURE ATTENTION ■ IMMEDIATE ATTENTION

INTERIOR/EXTERIOR	
NOTE ANY EXISTING BODY DAMAGE	
Lights (Head, Brake, Turn, Parking)	■ ■ ■
Windshield / Glass	■ ■ ■
Wipers	■ ■ ■
Horn / Interior Lights	■ ■ ■

TIRES			
TREAD DEPTH			
■ 7/32" or greater	■ 3/32" to 6/32"	■ 2/32" or less	
LF ■ ■ ■ 7/32"	RF ■ ■ ■ 7/32"		
LR ■ ■ ■ 8/32"	RR ■ ■ ■ 8/32"		
	Wear Pattern/ Damage	Air Pressure	Based on Mileage and Wear:
	LF ■ ■ ■	<input type="checkbox"/> BEFORE <input type="checkbox"/> SHOULD BE	<input type="checkbox"/> Alignment
	RF ■ ■ ■	LF <input type="checkbox"/> <input type="checkbox"/> 40	<input type="checkbox"/> Balance
	LR ■ ■ ■	RF <input type="checkbox"/> <input type="checkbox"/> 40	<input type="checkbox"/> Rotation
RR ■ ■ ■	LR <input type="checkbox"/> <input type="checkbox"/>	<input checked="" type="checkbox"/> New Tire	
	RR <input type="checkbox"/> <input type="checkbox"/>		

BATTERY	
■ ■ ■	

BRAKES	
BRAKE PADS / SHOES	
■ Over 5 mm (Disk) or 2 mm (Drum)	
■ 3-5 mm (Disk) or 1.01-2 mm (Drum)	
■ Less than 3 mm (Disk) or 1 mm (Drum)	
LF ■ ■ ■	
RF ■ ■ ■	
LR ■ ■ ■	
RR ■ ■ ■	

UNDERHOOD	
Oil Condition	■ ■ ■
Transmission Fluid	■ ■ ■
Power Steering / Brake Fluid	■ ■ ■
Coolant / Antifreeze	■ ■ ■
Air Filter	■ ■ ■
Cabin Filter	■ ■ ■
Belts	■ ■ ■

UNDER VEHICLE	
Brake Lines / Brake Hoses / Brake Cables / Fuel Lines	■ ■ ■
Suspension & Steering	■ ■ ■
Driveline (Axles / CV Shaft)	■ ■ ■
Rear Differential Fluid Level & Condition	■ ■ ■
Exhaust System / Shocks & Struts	■ ■ ■

COMMENTS	

Inspected by: [Signature] Date: 3/16/22