

2022



2022

# MULTI-POINT INSPECTION

VEH#: 17-519 Mileage: 75,572 Year/Make/Model: \_\_\_\_\_  
 WO#: 15504 VIN: \_\_\_\_\_ License: \_\_\_\_\_ email: \_\_\_\_\_

■ CHECKED AND OK      ■ FUTURE ATTENTION      ■ IMMEDIATE ATTENTION

### INTERIOR/EXTERIOR

NOTE ANY EXISTING BODY DAMAGE

|                                     |   |
|-------------------------------------|---|
| Lights (Head, Brake, Turn, Parking) | <span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span> |
| Windshield / Glass                  | <span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span> |
| Wipers                              | <span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span> |
| Horn / Interior Lights              | <span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span> |

### TIRES

#### TREAD DEPTH

■ 7/32" or greater      ■ 3/32" to 6/32"      ■ 2/32" or less

|  |  |  |
|--|--|--|
| LF <span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span> 8/32"<br>LR <span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span> 8/32" | RF <span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span> 8/32"<br>RR <span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span> 8/32" |  |
|--|--|--|

Wear Pattern / Damage

|    |   |
|----|---|
| LF | <span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span> |
| RF | <span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span> |
| LR | <span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span> |
| RR | <span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span> |

Air Pressure

|  |       |    |       |    |       |    |       |    |
|--|-------|----|-------|----|-------|----|-------|----|
| <span style="color: red;">■</span> (!)   |       |    |       |    |       |    |       |    |
| BEFORE    SHOULD BE  |       |    |       |    |       |    |       |    |
| <table style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 50%; border: 1px solid black; text-align: center;">LF 33</td> <td style="width: 50%; border: 1px solid black; text-align: center;">35</td> </tr> <tr> <td style="border: 1px solid black; text-align: center;">RF 33</td> <td style="border: 1px solid black; text-align: center;">35</td> </tr> <tr> <td style="border: 1px solid black; text-align: center;">LR 35</td> <td style="border: 1px solid black; text-align: center;">35</td> </tr> <tr> <td style="border: 1px solid black; text-align: center;">RR 35</td> <td style="border: 1px solid black; text-align: center;">35</td> </tr> </table> | LF 33 | 35 | RF 33 | 35 | LR 35 | 35 | RR 35 | 35 |
| LF 33  | 35    |    |       |    |       |    |       |    |
| RF 33  | 35    |    |       |    |       |    |       |    |
| LR 35  | 35    |    |       |    |       |    |       |    |
| RR 35  | 35    |    |       |    |       |    |       |    |

Based on Mileage and Wear:

Alignment

Balance

Rotation

New Tire

### BATTERY

■ ■ ■

### UNDERHOOD

|                              |   |
|------------------------------|---|
| Oil Condition <i>changed</i> | <span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span> |
| Transmission Fluid           | <span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span> |
| Power Steering / Brake Fluid | <span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span> |
| Coolant / Antifreeze         | <span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span> |
| Air Filter <i>changed</i>    | <span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span> |
| Cabin Filter                 | <span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span> |
| Belts                        | <span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span> |

### BRAKES

#### BRAKE PADS / SHOES

■ Over 5 mm (Disk) or 2 mm (Drum)  
■ 3-5 mm (Disk) or 1.01-2 mm (Drum)  
■ Less than 3 mm (Disk) or 1 mm (Drum)

|    |   |
|----|---|
| LF | <span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span> |
| RF | <span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span> |
| LR | <span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span> |
| RR | <span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span> |

### UNDER VEHICLE

|   |   |
|---|---|
| Brake Lines / Brake Hoses / Brake Cables / Fuel Lines | <span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span> |
| Suspension & Steering                                 | <span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span> |
| Driveline (Axles / CV Shaft)                          | <span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span> |
| Rear Differential Fluid Level & Condition             | <span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span> |
| Exhaust System / Shocks & Struts                      | <span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span> |

### COMMENTS

Next service replace front and rear brakes

Inspected by: Keith Date: 8-2-22