

2022



2022

MULTI-POINT INSPECTION

VEH#: 17-721 Mileage: 5581 Year/Make/Model: _____
 WO#: 15706 VIN: _____ License: _____ email: _____



CHECKED AND OK



FUTURE ATTENTION



IMMEDIATE ATTENTION

INTERIOR/EXTERIOR	
NOTE ANY EXISTING BODY DAMAGE	
Lights (Head, Brake, Turn, Parking)	☒ ☐ ☐
Windshield / Glass	☒ ☐ ☐
Wipers	☒ ☐ ☐
Horn / Interior Lights	☒ ☐ ☐

BATTERY	
☒ ☐ ☐	

UNDERHOOD	
Oil Condition	☒ ☐ ☐
Transmission Fluid	☒ ☐ ☐
Power Steering / Brake Fluid	☒ ☐ ☐
Coolant / Antifreeze	☒ ☐ ☐
Air Filter	☒ ☐ ☐
Cabin Filter	☒ ☐ ☐
Belts	☒ ☐ ☐

UNDER VEHICLE	
Brake Lines / Brake Hoses / Brake Cables / Fuel Lines	☒ ☐ ☐
Suspension & Steering	☒ ☐ ☐
Driveline (Axles / CV Shaft)	☒ ☐ ☐
Rear Differential Fluid Level & Condition	☒ ☐ ☐
Exhaust System / Shocks & Struts	☒ ☐ ☐

TIRES															
TREAD DEPTH															
☒ 7/32" or greater ☐ 3/32" to 6/32" ☐ 2/32" or less															
LF ☒ ☐ ☐ 10/32"	RF ☒ ☐ ☐ 10/32"														
LR ☒ ☐ ☐ 10/32"	RR ☒ ☐ ☐ 10/32"														
	<table border="1"> <thead> <tr> <th colspan="2">Wear Pattern/ Damage</th> <th colspan="2">Air Pressure</th> <th rowspan="2">Based on Mileage and Wear:</th> </tr> <tr> <th>LF</th> <th>RF</th> <th>LR</th> <th>RR</th> </tr> </thead> <tbody> <tr> <td>☒ ☐ ☐</td> <td>☒ ☐ ☐</td> <td>☒ ☐ ☐</td> <td>☒ ☐ ☐</td> <td> ☐ Alignment ☐ Balance ☐ Rotation ☐ New Tire </td> </tr> </tbody> </table>	Wear Pattern/ Damage		Air Pressure		Based on Mileage and Wear:	LF	RF	LR	RR	☒ ☐ ☐	☒ ☐ ☐	☒ ☐ ☐	☒ ☐ ☐	☐ Alignment ☐ Balance ☐ Rotation ☐ New Tire
Wear Pattern/ Damage		Air Pressure		Based on Mileage and Wear:											
LF	RF	LR	RR												
☒ ☐ ☐	☒ ☐ ☐	☒ ☐ ☐	☒ ☐ ☐	☐ Alignment ☐ Balance ☐ Rotation ☐ New Tire											

BRAKES	
BRAKE PADS / SHOES	
☒ Over 5 mm (Disk) or 2 mm (Drum) ☐ 3-5 mm (Disk) or 1.01-2 mm (Drum) ☐ Less than 3 mm (Disk) or 1 mm (Drum)	
LF ☒ ☐ ☐ RF ☒ ☐ ☐ LR ☒ ☐ ☐ RR ☒ ☐ ☐	

COMMENTS	

Inspected by: Glenn Anderson Date: 9-08-22