

2022



2022

MULTI-POINT INSPECTION

VEH#: 17-721 Mileage: 10,507 Year/Make/Model: _____
 WO#: 16154 VIN: _____ License: _____ email: _____



CHECKED AND OK




FUTURE ATTENTION



IMMEDIATE ATTENTION

INTERIOR/EXTERIOR


NOTE ANY EXISTING BODY DAMAGE



Lights (Head, Brake, Turn, Parking)




Windshield / Glass




Wipers



Horn / Interior Lights




BATTERY



UNDERHOOD

Oil Condition




Transmission Fluid




Power Steering / Brake Fluid



Coolant / Antifreeze



Air Filter



Cabin Filter



Belts



UNDER VEHICLE

Brake Lines / Brake Hoses /
Brake Cables / Fuel Lines

Suspension & Steering



Driveline (Axles / CV Shaft)



Rear Differential Fluid Level & Condition



Exhaust System / Shocks & Struts



TIRES

TREAD DEPTH

☒ 7/32" or greater ☐ 3/32" to 6/32" ☐ 2/32" or less

 LF ☒ ☐ ☐ 9/32" RF ☒ ☐ ☐ 9/32"

 LR ☒ ☐ ☐ 9/32" RR ☒ ☐ ☐ 9/32"
Wear Pattern/
DamageLF ☒ ☐ ☐RF ☒ ☐ ☐LR ☒ ☐ ☐RR ☒ ☐ ☐

Air Pressure



BEFORE SHOULD BE


LF ☐ 35RF ☐LR ☐ 35RR ☐Based on
Mileage
and Wear:☐ Alignment☐ Balance☐ Rotation☐ New Tire

BRAKES

BRAKE PADS / SHOES

☒ Over 5 mm (Disk)
or 2 mm (Drum)

☐ 3-5 mm (Disk)
or 1.01-2 mm (Drum)

☐ Less than 3 mm (Disk)
or 1 mm (Drum)
LF ☒ ☐ ☐RF ☒ ☐ ☐LR ☒ ☐ ☐RR ☒ ☐ ☐

COMMENTS

 Inspected by: Glenn Anderson Date: 11/2022