

Received

APR 14 2023

LCPW Motor Pool

2023



2023

MULTI-POINT INSPECTION

VEH#: 17-519 Mileage: 90310 Year/Make/Model: _____
WO#: 16873 VIN: _____ License: _____ email: _____

■ CHECKED AND OK ■ FUTURE ATTENTION ■ IMMEDIATE ATTENTION

INTERIOR/EXTERIOR	
NOTE ANY EXISTING BODY DAMAGE	
Lights (Head, Brake, Turn, Parking)	■ ■ ■
Windshield / Glass	■ ■ ■
Wipers	■ ■ ■
Horn / Interior Lights	■ ■ ■

TIRES			
TREAD DEPTH			
■ 7/32" or greater	■ 3/32" to 6/32"	■ 2/32" or less	
LF ■ ■ ■ _____/32"	RF ■ ■ ■ _____/32"		
LR ■ ■ ■ _____/32"	RR ■ ■ ■ _____/32"		
	Wear Pattern/Damage	Air Pressure	Based on Mileage and Wear: <input type="checkbox"/> Alignment <input type="checkbox"/> Balance <input type="checkbox"/> Rotation <input type="checkbox"/> New Tire
	LF ■ ■ ■	<input type="checkbox"/> BEFORE <input type="checkbox"/> SHOULD BE	
	RF ■ ■ ■	LF <u>35</u> <u>35</u>	
	LR ■ ■ ■	RF <u>38</u>	
RR ■ ■ ■	LR <u>38</u> <u>35</u>		
	RR <u>35</u>		

BATTERY	
■ ■ ■	

BRAKES	
BRAKE PADS / SHOES	
■ Over 5 mm (Disk) or 2 mm (Drum)	
■ 3-5 mm (Disk) or 1.01-2 mm (Drum)	
■ Less than 3 mm (Disk) or 1 mm (Drum)	
LF ■ ■ ■	
RF ■ ■ ■	
LR ■ ■ ■	
RR ■ ■ ■	

UNDERHOOD	
Oil Condition	■ ■ ■
Transmission Fluid	■ ■ ■
Power Steering / Brake Fluid	■ ■ ■
Coolant / Antifreeze	■ ■ ■
Air Filter	■ ■ ■
Cabin Filter	■ ■ ■
Belts	■ ■ ■

UNDER VEHICLE	
Brake Lines / Brake Hoses / Brake Cables / Fuel Lines	■ ■ ■
Suspension & Steering	■ ■ ■
Driveline (Axles / CV Shaft)	■ ■ ■
Rear Differential Fluid Level & Condition	■ ■ ■
Exhaust System / Shocks & Struts	■ ■ ■

COMMENTS

Inspected by: Celenn Date: 4-13-23