

Received

2023  
JUN 14 2023



2023

LCPW Motor Pool

### MULTI-POINT INSPECTION

VEH#: 13-117 Mileage: 59387 Year/Make/Model: \_\_\_\_\_

WO#: 17214 VIN: \_\_\_\_\_ License: \_\_\_\_\_ email: \_\_\_\_\_

CHECKED AND OK       FUTURE ATTENTION       IMMEDIATE ATTENTION

INTERIOR/EXTERIOR	
NOTE ANY EXISTING BODY DAMAGE	
Lights (Head, Brake, Turn, Parking)	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Windshield / Glass	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Wipers	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Horn / Interior Lights	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>

TIRES		
TREAD DEPTH		
<input checked="" type="checkbox"/> 7/32" or greater	<input type="checkbox"/> 3/32" to 6/32"	<input type="checkbox"/> 2/32" or less
LF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 7/32"	RF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 7/32"	
LR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 7/32"	RR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 7/32"	
	Wear Pattern / Damage	Air Pressure
	LF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<input type="checkbox"/>
	RF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	BEFORE SHOULD BE
	LR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	LF <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
RR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	RF <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	LR <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
		RR <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
		Based on Mileage and Wear:
		<input type="checkbox"/> Alignment
		<input type="checkbox"/> Balance
		<input type="checkbox"/> Rotation
		<input type="checkbox"/> New Tire

BATTERY	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	

BRAKES	
BRAKE PADS / SHOES	
<input checked="" type="checkbox"/> Over 5 mm (Disk) or 2 mm (Drum)	
<input type="checkbox"/> 3-5 mm (Disk) or 1.01-2 mm (Drum)	
<input type="checkbox"/> Less than 3 mm (Disk) or 1 mm (Drum)	
LF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
RF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
LR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
RR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	

UNDERHOOD	
Oil Condition	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Transmission Fluid	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Power Steering / Brake Fluid	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Coolant / Antifreeze	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Air Filter	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Cabin Filter	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Belts	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>

UNDER VEHICLE	
Brake Lines / Brake Hoses / Brake Cables / Fuel Lines	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Suspension & Steering	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Driveline (Axles / CV Shaft)	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Rear Differential Fluid Level & Condition	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Exhaust System / Shocks & Struts	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>

COMMENTS

Inspected by: Glenn Anderson Date: 6-13-23