

Received

JUL 26 2023

LCPW Motor Pool

2023



2023

MULTI-POINT INSPECTION

VEH#: 17-721 Mileage: 22321 Year/Make/Model: _____
 WO#: 17165 VIN: _____ License: _____ email: _____



CHECKED AND OK




FUTURE ATTENTION



IMMEDIATE ATTENTION

INTERIOR/EXTERIOR

NOTE ANY EXISTING BODY DAMAGE



Lights (Head, Brake, Turn, Parking)	☒	☐	☐
Windshield / Glass	☒	☐	☐
Wipers	☒	☐	☐
Horn / Interior Lights	☒	☐	☐

BATTERY



UNDERHOOD

Oil Condition <u>changed</u>	☒	☐	☐
Transmission Fluid	☒	☐	☐
Power Steering / Brake Fluid	☒	☐	☐
Coolant / Antifreeze	☒	☐	☐
Air Filter	☒	☐	☒
Cabin Filter <u>Replaced</u>	☒	☐	☒
Belts	☒	☐	☐

UNDER VEHICLE

Brake Lines / Brake Hoses / Brake Cables / Fuel Lines	☒	☐	☐
Suspension & Steering	☒	☐	☐
Driveline (Axles / CV Shaft)	☒	☐	☐
Rear Differential Fluid Level & Condition	☒	☐	☐
Exhaust System / Shocks & Struts	☒	☐	☐

TIRES

TREAD DEPTH

☒ 7/32" or greater	☐ 3/32" to 6/32"	☐ 2/32" or less
LF ☒ ☐ ☐ 7/32"	RF ☒ ☐ ☐ 7/32"	
LR ☒ ☐ ☐ 7/32"	RR ☒ ☐ ☐ No tread	

Wear Pattern/
Damage

LF ☒ ☐ ☐
RF ☒ ☐ ☐
LR ☒ ☐ ☐
RR ☒ ☐ ☐

Air Pressure



	BEFORE	SHOULD BE
LF		
RF	35	
LR		
RR	35	

Based on
Mileage
and Wear:


- ☐ Alignment
☐ Balance
☐ Rotation
☐ New Tire

BRAKES

BRAKE PADS / SHOES

- ☒ Over 5 mm (Disk)
or 2 mm (Drum)
☐ 3-5 mm (Disk)
or 1.01-2 mm (Drum)
☐ Less than 3 mm (Disk)
or 1 mm (Drum)

LF ☒ ☐ ☐
RF ☒ ☐ ☐
LR ☒ ☐ ☐
RR ☒ ☐ ☐



COMMENTS

Inspected by: Trevor Date: 7-18-23