


LEWIS COUNTY MOTOR POOL MULTI- POINT INSPECTION FORM

VEH# 17-519 WO# 18195 ODOM 110,083

	Checked and OK at this time May
	INTERIOR / EXTERIOR
	Lights
	Wiper Blade Operation Front and Rear
	Washer Fluid Windshield Condition
✓	Upholstery / Carpet / Mats / Mirrors Glass
✓	Parking Brake
	Safety Bag / Tri Kit / 1st Aid Kit / Fire Ext.
	Cabin Filter
UNDER VEHICLE	
/	Suspension
✓	Steering Gear Box / Linkage and Boots Ball Joints / Dust Covers
/	Muffler / Exhaust Pipes / Mounting
/	Engine Oil and / or Fluid Leaks
/	Drive Shaft Boots / CV Boots / U-Joints
/	Transmission / Differentil / Transfer Case Check Fluid Level / Condition / Leaks
/	Fuel Lines / Connections / Tank Band
	Fuel Tank Vapor Vent System Hoses

NOTES

Could not access battery to check condition



TECHNICIAN Trevor

DATE 1-4-2024