

LEWIS COUNTY MOTOR POOL **MULTI- POINT INSPECTION FORM**

VEH# 17-519 **WO#** 18567 116562 ODOM

	Checked and OK at this time May
	INTERIOR / EXTERIOR
	Lights
	Wiper Blade Operation Front and Rear Washer Fluid Windshield Condition
/	Upholstery / Carpet / Mats / Mirrors Glass Parking Brake
	Safety Bag / Tri Kit / 1st Aid Kit / Fire Ext.
/	Cabin Filter
	UNDER VEHICLE
	UNDER VEHICLE Suspension
	Suspension Steering Gear Box / Linkage and Boots Ball Joints / Dust Covers
	Suspension Steering Gear Box / Linkage and Boots Ball Joints / Dust Covers Muffler / Exhaust Pipes / Mounting
	Suspension Steering Gear Box / Linkage and Boots Ball Joints / Dust Covers Muffler / Exhaust Pipes / Mounting Engine Oil and / or Fluid Leaks

NOTES:

