


LEWIS COUNTY MOTOR POOL MULTI- POINT INSPECTION FORM

VEH# <u>13-117</u> WO# <u>19256</u> ODOM <u>71621</u>

	Checked and OK at this time
	INTERIOR / EXTERIOR
	Lights
	Wiper Blade Operation Front and Rear
	Washer Fluid Windshield Condition
	Upholstery / Carpet / Mats / Mirrors Glass
	Parking Brake
	Safety Bag / Tri Kit / 1st Aid Kit / Fire Ext.
	Cabin Filter
	UNDER VEHICLE
	Suspension
	Steering Gear Box / Linkage and Boots Ball Joints / Dust Covers
	Muffler / Exhaust Pipes / Mounting
/	Engine Oil and / or Fluid Leaks
	Drive Shaft Boots / CV Boots / U-Joints
	Transmission / Differentil / Transfer Case
	Check Fluid Level / Condition / Leaks Fuel Lines / Connections / Tank Band
	Fuel Tank Vapor Vent System Hoses

NOTES:



TECHNICIAN ian DATE 8-5-24