

LEWIS COUNTY MOTOR POOL MULTI- POINT INSPECTION FORM

VEH# 17-721 WO# 19296 ODOM 43,967

	Checked and OK at this time	May
	INTERIOR / EXTERIOR	
/	Lights	
	Wiper Blade Operation Front and Rear	
	Washer Fluid Windshield Condition	
	Upholstery / Carpet / Mats / Mirrors	
	Glass Parking Brake	
	Safety Bag / Tri Kit / 1st Aid Kit / Fire Ext.	
	Cabin Filter	
	UNDER VEHICLE	
	Suspension	
/	Steering Gear Box / Linkage and Boots Ball Joints / Dust Covers	
/	Muffler / Exhaust Pipes / Mounting	
	Engine Oil and / or Fluid Leaks	
	Drive Shaft Boots / CV Boots / U-Joints	
	Transmission / Differentil / Transfer Case Check Fluid Level / Condition / Leaks	
	Fuel Lines / Connections / Tank Band	
	Fuel Tank Vapor Vent System Hoses Inspect Nuts and Bolts on Body Chassis	

NOTES:

