


LEWIS COUNTY MOTOR POOL MULTI- POINT INSPECTION FORM

VEH# 17-519 WO# 19532 ODOM 130585

Checked and OK at this time	May
INTERIOR / EXTERIOR	
Lights	
Wiper Blade Operation Front and Rear Washer Fluid	
Windshield Condition	
Upholstery / Carpet / Mats / Mirrors Glass	
Parking Brake	
Safety Bag / Tri Kit / 1st Aid Kit / Fire Ext.	
Cabin Filter	
UNDER VEHICLE	
Suspension	
Steering Gear Box / Linkage and Boots Ball Joints / Dust Covers	
Muffler / Exhaust Pipes / Mounting	
Engine Oil and / or Fluid Leaks	
Drive Shaft Boots / CV Boots / U-Joints	
Transmission / Differentil / Transfer Case Check Fluid Level / Condition / Leaks	
Fuel Lines / Connections / Tank Band Fuel Tank Vapor Vent System Hoses	
Inspect Nuts and Bolts on Body Chassis	

NOTES:



TECHNICIAN ian DATE 10-14-24