

LEWIS COUNTY MOTOR POOL MULTI- POINT INSPECTION FORM

VEH# 17-721 WO# 19893 ODOM49,032

	Checked and OK at this time	May
	INTERIOR / EXTERIOR	
	Lights	
✓	Wiper Blade Operation Front and Rear Washer Fluid Windshield Condition	
√	Upholstery / Carpet / Mats / Mirrors Glass Parking Brake	
	Safety Bag / Tri Kit / 1st Aid Kit / Fire Ext.	
	Cabin Filter	
	UNDER VEHICLE	
\checkmark	Suspension	
√	Steering Gear Box / Linkage and Boots Ball Joints / Dust Covers Muffler / Exhaust Pipes / Mounting	
\checkmark	Engine Oil and / or Fluid Leaks	
	Drive Shaft Boots / CV Boots / U-Joints	
	Transmission / Differentil / Transfer Case Check Fluid Level / Condition / Leaks	
	Fuel Lines / Connections / Tank Band Fuel Tank Vapor Vent System Hoses	
	Inspect Nuts and Bolts on Body Chassis	

NOTES:

